



Patriot Harris – System Photos

October 2, 2011

Refuse Outlet Spillway – Post KR-DP0168 Feed



Refuse Outlet Spillway – Post KR-DP0168 Feed



Refuse Outlet Spillway – Post KR-DP0168 Feed



Refuse Outlet Spillway – Post KR-DP0168 Feed

No Staining on Tall Grasses



Refuse Outlet Spillway – Post KR-DP0168 Feed



Refuse Outlet Spillway – Post KR-DP0168 Feed

KR-DP0168 Mixing Zone



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Staining Evident in Creekbed



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Staining Evident in Creekbed



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Close-up of Stained Logs in Creekbed



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Stained Tall Grasses in Creekbed



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Close-up of Stained Tall Grasses in Creekbed



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Staining Evident on Submerged Tree Limb



Refuse Outlet Spillway – Pre KR-DP0168 Feed

Close-up of Submerged Tree Limb



Main Outlet – Good Clarity



Main Outlet

Close-up of Discharge into Creekbed



Main Outlet

Outlet Rock Slabs – No Staining

